



# Air Dryer Guide

## BA5284



**Fits:** Van Hool CL915, CL916 Buses with DAF Engines; DAF Trucks  
**Replaces:** DAF 1681575, 1821580; Donaldson P951411  
**Thread:** M41 x 1.5  
**O.D.:** 5 7/16 (138.1)  
**Length:** 6 19/32 (167.5)  
**F. Gskt.:** [1] Included  
**I. Gskt.:** [1] Included  
**Related To:** BA5376 (Dessicant Version)

## BA5371



**Fits:** Freightliner Trucks  
**Replaces:** Haldex DA33120  
**Thread:** 2 1/2-12  
**O.D.:** 5 7/32 (132.6)  
**Length:** 6 5/8 (168.3)  
**I. Gskt.:** [1] Included

## BA5372



**Contains:** [4] Bolts  
[4] Lock Washers  
Grease Tube  
**Fits:** Freightliner, IHC Trucks  
**Replaces:** Bendix 103981, 104358  
**O.D.:** 4 17/32 (115.1)  
Lid 5 27/32 (148.4)  
**Length:** 9 23/32 (246.9)  
**O-Ring:** [1] Included

## BA5373



**Contains:** Grease Tube  
**Fits:** Ford, Freightliner, Hino, IHC, Kenworth, Mack, Peterbilt, Volvo Trucks  
**Replaces:** Bendix 65624, 109493  
**Thread:** 1 1/4-17  
**O.D.:** 7 9/32 (184.9)  
Flange 8 3/8 (212.7)  
**Length:** 7 17/32 (191.3)  
**O-Ring:** [2] Attached  
[2] Included

## BA5374



**Fits:** DAF, Freightliner, IHC, Iveco, Kenworth, M.A.N., Mack, Mercedes-Benz, Peterbilt, R.V.I., Volvo Trucks; Kassbohrer, Setra Buses  
**Replaces:** Iveco 2992261; Hengst T250W; Mann & Hummel TB1374x  
**Thread:** M39 x 1.5  
**O.D.:** 5 1/2 (139.7)  
**Length:** 6 19/32 (167.5)  
**I. Gskt.:** [1] Included  
**O-Ring:** [1] Included  
**Related To:** BA5379 (Coalescer Version)

## BA5375



**Fits:** R.V.I., Scania Trucks  
**Replaces:** Scania 1384549, 1455253  
**Thread:** 1 1/4-11 BSP-PL  
**O.D.:** 5 1/2 (139.7)  
**Length:** 6 31/32 (177.0)  
**I. Gskt.:** [1] Included  
**O-Ring:** [1] Included  
**Related To:** BA5378 (Coalescer Version)

## BA5376



**Fits:** DAF Trucks  
**Replaces:** DAF 1391510; Hengst T200W  
**Thread:** M41 x 1.5  
**O.D.:** 5 1/2 (139.7)  
**Length:** 5 15/32 (138.9)  
**I. Gskt.:** [1] Included  
**O-Ring:** [1] Included  
**Related To:** BA5284 (Coalescer Version)

## BA5377



**Contains:** Threaded Stud: 5/8-11  
Grease Tube  
**Fits:** Blue Bird, Thomas Buses; Autocar, Capacity, Freightliner, IHC, Kenworth, Mack, Oshkosh, Peterbilt, Sterling, Western Star Trucks  
**Replaces:** Bendix 107794, 107796  
**O.D.:** 4 17/32 (115.1)  
Lid 5 27/32 (148.4)  
**Length:** 10 23/32 (272.3)  
**O-Ring:** [2] Included

## BA5378



**Fits:** Scania Trucks  
**Replaces:** Scania 1774598; Donaldson P783753  
**Thread:** 1 1/4-11 BSP  
**O.D.:** 5 11/32 (135.7)  
**Length:** 7 (177.8)  
**I. Gskt.:** [1] Included  
**O-Ring:** [1] Included  
**Related To:** BA5375 (Dessicant Version)

## BA5379



**Fits:** M.A.N., Mercedes-Benz, R.V.I., Volvo Trucks  
**Replaces:** Volvo 20557234, 20972915; DAF 1506635; M.A.N. 81521086025  
**Thread:** M39 x 1.5  
**O.D.:** 5 3/8 (136.5)  
**Length:** 6 19/32 (167.5)  
**I. Gskt.:** [1] Included  
**O-Ring:** [1] Included  
**Related To:** BA5374 (Dessicant Version)

## BA5566



**Contains:** Left Hand Threads  
**Fits:** Volvo Trucks  
**Replaces:** Knorr-Bremse K005686, K014712, K039453; Renault 5001865404, 7421267793; Volvo 20754416, 21267818; Wabco 4329012452; Mahle AL26  
**O.D.:** 5 3/8 (136.5)  
**Length:** 6 19/32 (167.5)  
**I. Gskt.:** [1] Included  
**O-Ring:** [1] Included

## BA5592



**Fits:** Freightliner, Mack, Volvo, Western Star Trucks  
**Replaces:** Volvo 8235R950068, 85110799  
**Thread:** M39 x 1.5  
**O.D.:** 5 1/2 (139.7)  
**Length:** 6 19/32 (167.5)  
**I. Gskt.:** [1] Included  
**O-Ring:** [1] Included

## BA16000



**Contains:** [4] Bolts and Nuts  
 [4] Locking Pins  
**Fits:** Volvo Dump Trucks, Excavators; European FH Serie Trucks  
**Replaces:** Evobus 4294695; Haldex 78964, 83212, 92528, 93522; Iveco 42535061; Volvo 20424148, 20546795, 20773824  
**O.D.:** 6 (152.4)  
**Length:** 6 3/8 (161.9)  
**O-Ring:** [1] Included

# QUICK CROSS-REFERENCE

BALDWIN	BENDIX	DONALDSON	FLEETGUARD	HALDEX	LUBER-FINER	WABCO
BA5284	-	P951411	-	-	-	4329012462
BA5371	-	-	-	DA33120, 201160	-	-
BA5372	103981, 104358	-	-	-	-	-
BA5373	65624, 109493	-	-	-	-	-
BA5374	109994, 5008414, 5008415	P781466	AF27817	31004109	LFP8654	4324202202
BA5375	-	-	-	-	LFP5375	4324152202
BA5376	-	P951417	AF27853	-	-	-
BA5377	107794, 107796	-	-	-	-	-
BA5378	-	P783753	-	-	-	4324109282, 4329012282
BA5379	-	P951413	-	-	LFP8845	4329012252
BA5566	-	-	-	-	-	4329012452
BA5592	-	P951413	-	-	-	R950068
BA16000	-	-	-	78964, 83212, 92528, 93522	-	-



800.822.5394 | baldwinfilter.com

Designed and manufactured in the USA.

Form 375 (R 8/17) © 2017 Baldwin Filters, a Parker Hannifin Company

Printed in the U.S.A.



**WARNING:** These products can expose you to chemicals, including Diisononyl Phthalate, Carbon black extracts, Nickel, 1,3 Butadiene, Ethylene Oxide, Epichlorohydrin, which are known to the State of California to cause cancer, and Bisphenol-A, Ethylene Glycol, Ethylene Oxide, 1,3 Butadiene, Epichlorohydrin, which are known to the State of California to cause birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).