

**FLEETGUARD**

**V. Cross Reference by Manufacturer**

**CATERPILLAR**

MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.
<b>AC</b>		<b>ATLAS</b>		BF7922	FF5612	95358MP	FF5018(12)OR	1457434068	FF5018	413363A1	90366COR
PF61	LF3945	392 9440 1/1	LF3555	BF-940	FF5226	Upgrade: FS1221		Upgrade: FS1221			90366POR
Upgrade: LF16104		6001957	AF25724	BF-988	FF5018		FF5052(12)	1457434072	FF5018	47107867	AF26284
TP-1200	FF5226	6044338	AF25729	Upgrade: FS1221		Upgrade: FS1251		Upgrade: FS1221		47131180	HF6553
TP-943	FF5033	6044340	AF25730	BF-993	FF5018	95390	FF5226	1457434073	FF5018	504054011	FS19821
TP-959L	FF5616	6069019	LF3914	Upgrade: FS1221		95585	FS19579E	Upgrade: FS1221		82034441	AF25457
TP-961	FF5018	<b>ATLAS COPCO</b>		BK6663	FF5507	96043	FF246	1 457 434 120	FF5074	8743556	FS19821
Upgrade: FS1221		0116-243-00	FF5018	BT-366-10	HF6535	<b>BITELLI</b>		1457434154	FF5018	A-77470	FF5052AND
XD-25	FF5018	Upgrade: FS1221		BT8512	HF28989	225058	FF5052	Upgrade: FS1221		Upgrade: FS1251	
Upgrade: FS1221		1310.0322.44	FF5052	BT9362MPG	HF6555	Upgrade: FS1251		1 457 434 190	FF5018	J-903640	FF5052
<b>AG CHEM EQUIPMENT</b>		Upgrade: FS1251		BT9363MPG	HF6518	264005	FF5018	Upgrade: FS1221		Upgrade: FS1251	
3903640	FF5052	1310035646	90355BOR	BT9368-MPG	HF40003	Upgrade: FS1221		0451103314	LF785	J931063	FF5052
Upgrade: FS1251		Upgrade: FS1251		BT9369-MPG	HF29035			9455160352	FF5018	Upgrade: FS1251	
709935	FF5052	1310035646	90355COR	BT9371MPG	HF6777	<b>BIURRARENA</b>		Upgrade: FS1221		KSH0932	AF25523
Upgrade: FS1251		1614 8747 00	LF3788	P7106	LF3517	<b>SEE GURIA</b>		<b>BUHLER</b>		P105564	FF5018
<b>AGCO</b>		1614874799	LF3788	PA4666	AF25702	14-4115	FF5052	00088834	FF5052	Upgrade: FS1221	
<b>SEE ALLIS-CHALMERS</b>		3222309421	FF5319	PA4701	AF26153	Upgrade: FS1251		Upgrade: FS1251		P-150564	FF5018
1504385	83719NOR	3222309422	FS19591	PA4903	AF25353			9626900	204163S	Upgrade: FS1221	
2020805	90366POR	3222317948	LF691A	PA5333	AF1773	<b>BLAW-KNOX</b>		<b>CARQUEST</b>		V-37545	FF5018
	90366COR	Upgrade: LF3566		PA5339	AF26231	<b>SEE INGERSOLL-RAND</b>		86124	FF5033	Upgrade: FS1221	
2055366	90368POR	Upgrade: LF9691A		PA5340	AF26144	54517693	FF5074	86358	FF5018OR	76094176	HF6587
	90368COR	3718002828	FF5018	PA5341	AF26145	58831686	FF5018	Upgrade: FS1221		Upgrade: FS1221	
4300400M1	HF28919	5540108600	AF851M	PF7654	FS19579E	Upgrade: FS1221		FF5052		FF5052	
4303303M1	HF7952	5541125300	AF421M	PF7779	FS19684E	90140-002-00	FF5018	86358MP	FF5018(12)OR	72110719	HF7955
72501530	FF5052	9709-0005-20	FF5018	PF7910	FF4141	Upgrade: FS1221		Upgrade: FS1221		Upgrade: FS1221	
Upgrade: FS1251		Upgrade: FS1221		PT9361	HF7304	90141-002-00	FF5052	FF5052(12)		FF5052(12)	
<b>AIR REFINER</b>		9721-0337	FF5018	PT9374	HF28917	86390	FF5226	Upgrade: FS1251		86390	FF5226
ARH-0883LV05	HF35184	Upgrade: FS1221		RS3988	AF25436	86585	FS19579E	86648	FS19865	86777	FF5052
PF-5018	FF5018	3718002828	FF5018	RS4646	AF26330	86777	FF5052	87798	AF25955	Upgrade: FS1251	
Upgrade: FS1221		5540108600	AF851M	RS4803	AF26250	<b>BLOUNT</b>		89043	FF246		
<b>ALCO</b>		5541125300	AF421M	RS4966	AF25631	10013902	90354POR	<b>CARRARO</b>		41022	FF5018
SP821	FF5018	9709-0005-20	FF5018	RS5332	AF26249	Upgrade: FS1221		Upgrade: FS1221		Upgrade: FS1221	
Upgrade: FS1221		9721-0337	FF5018	RS5334	AF25957	8606006	FF5052	20-11-9182C	LF9030	20-11-9182C	LF9030
SP903	FF5226	Upgrade: FS1221		RS5335	AF25618	Upgrade: FS1251		<b>CARRIER</b>		20-11-9182C	LF9030
<b>ALLIANCE</b>		3929440	LF3555	RS5342	AF25653	<b>BOBCAT</b>		<b>CARRIER</b>		20-11-9182C	LF9030
ABPN83328345	AF25697	441887	FF5018	RS5343	AF25476	<b>SEE CLARK</b>		<b>CASE</b>		20-11-9182C	LF9030
<b>ALLIS-CHALMERS</b>		441923	FF5018	RS5351	AF25634	<b>SEE INGERSOLL-RAND</b>		<b>SEE J.I. CASE</b>		20-11-9182C	LF9030
SEE FIAT-ALLIS		4613418	FF5074	<b>BEHRINGER FLUID SYSTEMS, INC</b>		<b>37435.5</b>		<b>SEE IHC</b>		20-11-9182C	LF9030
61142392	FF5018	6001955	AF25723	<b>BELL</b>		<b>6678233</b>		<b>SEE INTERNATIONAL TRUCKS</b>		20-11-9182C	LF9030
Upgrade: FS1221		221392	FF5052OR	<b>BENATI</b>		<b>6681474</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
61142397	FF5018	Upgrade: FS1251		1821101	FF5018	<b>6681475</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
Upgrade: FS1221		ABP3003063	FF5052	Upgrade: FS1221		<b>6681475</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
61674455	FF5018	Upgrade: FS1251		1821124	FF5052	<b>3003054</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
Upgrade: FS1221		1041572	HF6535	Upgrade: FS1251		<b>Upgrade: FF5333</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
99100083	FF5018	<b>BALDWIN</b>		1829101	FF5018	<b>31780205</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
Upgrade: FS1221		B1363	FS19737	Upgrade: FS1221		<b>Upgrade: FF5052</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
99102121	FF5226	B7026-MPG	HF28812	<b>BERING</b>		<b>Upgrade: FS1251</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
Upgrade: FS1221		B7327	LF16117	<b>BIG A</b>		<b>Upgrade: FS1251</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
<b>AP LOCKHEED</b>		BD7325	LF16226	<b>SEE AMERICAN PARTS</b>		<b>05711729</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
AP-1081	FF5018	BF1351-SP	FS19843	<b>2069</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
Upgrade: FS1221		BF1363	FS19737	<b>3323</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
APF-3197A	FF5018	BF1365	FS19821	<b>3344</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
Upgrade: FS1221		BF1366	FS19735	<b>95124</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
LK-1081	FF5018	BF1367	FS19597	<b>95195</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
Upgrade: FS1221		BF7524	FF5052	<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
<b>ARLON</b>		Upgrade: FS1251		<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
SEE PARKER		BF7786D	FS19865	<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
TXX3-10-B	HF6306	BF-782	FF5033	<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
Upgrade: FS1221		BF-788	FF5052	<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
<b>ASAHI</b>		Upgrade: FS1251		<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
DF-7751	FF5226	BF7915	FF5040	<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
		BF7917	FF5580	<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
		BF7919	FF5427	<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030
		BF7921	FS19560	<b>95358</b>		<b>Upgrade: FS1221</b>		<b>SEE STEIGER</b>		20-11-9182C	LF9030

Error! Reference source not found.

**CATERPILLAR**

**V. Cross Reference by Manufacturer**

**FLEETGUARD**

MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.
<b>CAV (LUCAS-CAV)</b>		<b>CLARK</b>		3934763	FF42000	1902132	AF1843	P551042	LF3795	<b>DYNAHOE</b>	
494	FF5074 <sup>OR</sup>	1992367B	FF5018	3942470	FS19579E	2394637	AF1843	P551771	FF5621	499519	HF6417
Upgrade: FS1221	FF5018	Upgrade: FS1221		394521300	FS19579E	4144966	AF1843	P552422	HF6201	<b>DYNAPAC</b>	
7111/494	FF5074 <sup>OR</sup>	4111378	FF5018	3949947	FS19579E	42481020	AF1843	P55-3004	FF5018	212385	FF5052
Upgrade: FS1221	FF5018	Upgrade: FS1221		3964295	FS19579E	0.900.0204.2	AF25352	Upgrade: FS1221		Upgrade: FS1251	
7176/494	FF5074 <sup>OR</sup>	913557	FF5052	3974365	FS19579E	0.900.0204.3	AF25558	P55-3045	FF5422	499531	AF988
Upgrade: FS1221	FF5018	Upgrade: FS1251		3978040	FF5421	0.900.0389.8	ST1040	P55-5095	FF5095	<b>EPPENSTEINER</b>	
		<b>COLES</b>		3978133	3951006S	<b>DIAMOND</b>		P564424	AF4884	2.225 G40 2V	ST1762
		8767113	FF5018	4096196	LF9325	FD6221	FF5018	P564859	HF28948	2.32 P25 A00-0-A	ST2264
		Upgrade: FS1221		4096199	WF2054	Upgrade: FS1221		P606762	AF25780	<b>EUCLID</b>	
		<b>COMEX</b>		4096308	FS1006	FD8235	FF5018	P607097	AF25621	E12978047	FF5616
		M 0005 DH25	ST1523	4946497	AF26173	Upgrade: FS1221		P607223	AF441	<b>EVOBUS</b>	
		M 0008 DH25	ST1524	<b>CUMMINS HOUSINGS</b>		<b>DIGOMA</b>		P607233	AF1634	SEE KASSBOHRER	
		P 8900 D13N3	HF30518	3949947	FS19579E	DGMK/23	FF5074	P607251	AF1617	8.311.150.192	AF25626
		P 9800 D13N10	HF30290	3964295	FS19579E	DGMK731	FF5018	P607261	AF4855	<b>FACET</b>	
		<b>COOPERS</b>		<b>CUMMINS POWER GENERATION LTD</b>		Upgrade: FS1221		P607269	AF1870	1746925	HF28778
		ACE 179	AF25733	0122-0894	LF3706	<b>DINA CAMIONES</b>		P607293	AF1739 <sup>AND</sup>	<b>FAHR</b>	
		ACE 180	AF25695	0140-3359	AH19076	110B070240	90378B <sup>OR</sup>	AF1747K	AF25337M	1160243MZ	FF5018
		AEM2928	AF26241	0140-3550	AH8742	110B070250	90358B <sup>OR</sup>	AF1777K	AF25648	Upgrade: FS1221	
		AEM2938	AF26165	0140-3553	AH19092	<b>DITCH WITCH</b>		AF1777K	AF25653	<b>FAIREY ARLON</b>	
		AEM 2946	AF26261	0140-3596	AH19259	195813	FF5018	P610903	AF25337M	170-L-105H	HF30065
		AEM 2948	AF26246	0140-3604	AH19070	Upgrade: FS1221		P610905	AF25648	170-L-110H	HF30668
		AEM 2954	AF26204	0140-3737	AH19115	FFD31 A03	HF6539	P763535	HF6553	170-L-120H	HF30269
		AES 2617	AF25317	0140-3833	AH19072	FFD31 A06	HF6539	P764260	HF7952	170-L-1FFH	HF30269
		AES 2955	AF26245	0149-2752	FF5103	<b>DOMANGE</b>		P777156	AF25045M	170-L-205H	HF30216
		AG1404	AF25754	C240 0007	AF25688	FD31 A03	HF6539	P77-9379	FF5018	170-Z-105H	HF30065
		AZF003	FF5018	<b>DAEWOO</b>		FD31 A06	HF6539	Upgrade: FS1221		170-Z-110H	HF30668
		Upgrade: FS1221		<b>SEE GMC</b>		<b>DONALDSON</b>		P77-9451	FF5033	170-Z-120H	HF30269
		AZF003 (FUEL)	FF5018	474-00021	HF35140	FFP55-0440	FF5052	P781530	AF4645	170-Z-122H	HF30065
		Upgrade: FS1221		65.05510.5008	LF3633	Upgrade: FS1251		P 78-4682	AF25830	170-Z-123H	HF30668
		AZF300	FF5052	<b>DAIHATSU</b>		FFP55-0943	FF5033	P785522	AF26244	170-Z-1FFH	HF30269
		Upgrade: FS1251		2330337307	FF5226	FFP55-3004	FF5018	<b>DONGFENG MOTOR CORPORATION</b>		170-Z-110H	HF30668
		AZF830	FF5052	23303-87307-000	FF5226	Upgrade: FS1221		11092.D-030	AF25267	170-Z-120H	HF30269
		Upgrade: FS1251		<b>DAVCO</b>		FFP55-5095	FF5095	1109D5-030	AF25266	170-Z-122H	HF30065
		FEM4263	FS19605	101377	FF5052	G057511	AH19084	1109N-020	AF25270	170-Z-123H	HF30668
		FEM 4264	FF5463	Upgrade: FS1251		G057514	AH19085	1109N-030	AF25271	170-Z-1FFH	HF30269
		FSM4027	FF5226	232053RL	FH23215	G065411	AH19090	1109N12-020	AF25276	170-Z-205H	HF30216
		FSM4118	FF5074	<b>DAIWA</b>		G065424	AH19088	1109N12-030	AF25277	170-Z-222H	HF30216
		FSM4188	FF5647	<b>DELUXE</b>		G065433	AH19089	1109QE-020	AF25362	270-L-105H	HF30192
		FSM4239	FF5366	627	FF5018	G070018	AH19094	<b>DONGFENG NISSAN DIESEL</b>		270-L-122H	HF30192
		FSM 4266	FF5625	Upgrade: FS1221		G070019	AH19091	16546-96064	AF25452	270-L-201H	HF30095
		LSF5160	CS41000	<b>DAVCO</b>		G070020	AH19093	<b>DONIT</b>		270L205A	HF30220
		LSF5202	CS41005	101377	FF5052	G082525	AH19096	43 21 07	FF5018 <sup>OR</sup>	270-L-222A	HF30220
		LSF5203	CS41003	Upgrade: FS1251		G082527	AH19095	Upgrade: FS1221		270-Z-105H	HF30192
		Z75	FF5018	232053RL	FH23215	G082528	AH19097	FF5074		270-Z-110H	HF30714
		Upgrade: FS1221		<b>DEMAG</b>		G140054	AH19072	432121	FF5018 <sup>OR</sup>	270-Z-122H	HF30192
		<b>CROSLAND</b>		<b>SEE KOMATSU</b>		J9606	90356A	Upgrade: FS1221		270-Z-201H	HF30095
		5004	FF5226	11481186	FF5018	P16-4429	HF35184	FF5074		270-Z-205A	HF30220
		5035	FF5018	Upgrade: FS1221		P16-4580	HF35184	FF5018 <sup>OR</sup>		270-Z-221H	HF30095
		Upgrade: FS1221		<b>DEMAG</b>		P167891	HF30793 <sup>14</sup>	FF5074		270-Z-222A	HF30220
		658	FF5018	<b>SEE KOMATSU</b>		P172655	FF5052	FF5074		370-L-110H	HF30700
		Upgrade: FS1221		11481186	FF5018	Upgrade: FS1251		FF5074		370-L-123H	HF30700
		<b>CRUSADER</b>		Upgrade: FS1221		P173033	HF30220	FF5018 <sup>OR</sup>		370-L-205H	HF30233
		<b>SEE GMC</b>		20609140	FF5018	P174792	HF30109	FF5074		370-L-210H	HF30724
		22687	FF5059	Upgrade: FS1221		P18-2099	AF872M	FF5018 <sup>OR</sup>		370-L-223H	HF30724
		<b>CUMMINS</b>		4771869	FF5113	P228498	AF25664	FF5074		370-L-2FFH	HF30429
		0140-3288-02	AH19266	Upgrade: FS1221		P537355	AF26330	FF5074		370-L-301H	HF30098
		3166554	LF516	4771869	FF5113	P55-0127	FF5226	FF5074		370-L-305H	HF30277
		3166555	FF108	005 002 74	FF5018	P550430	FS19579E	FF5074		370-L-310H	HF30760
		3890707	FF5052	Upgrade: FS1221		P55-0440	FF5052	FF5074		370-Z-110H	HF30700
		Upgrade: FS1251		055 001 74	FF5113	Upgrade: FS1251		FF5074		370-Z-123H	HF30700
		3903640	FF5052	055 002 74	FF5018	P550491	FF5167	FF5074		370-Z-205H	HF30233
		Upgrade: FS1251		Upgrade: FS1221		P550496	FF5425	FF5074		370-Z-210H	HF30724
		3910469	90354C <sup>OR</sup>	<b>DEUTZ AG</b>		P550505	LF3945	FF5074		370-Z-220H	HF30429
		Upgrade: FS1251		<b>SEE</b>		Upgrade: LF16104		FF5074		370-Z-222H	HF30233
		3931063	FF5052	<b>KHD(KLOCKNER-HUMBOLDT-DEUTZ)</b>		P550506	FS19583	FF5074		370-Z-223H	HF30724
		Upgrade: FS1251		01181917	FF5018	P550508	FF5662	FF5074		370-Z-2FFH	HF30429
		3931065	FF5052	Upgrade: FS1221		P550582	HF7304	FF5074		370-Z-301H	HF30098
		Upgrade: FS1251		<b>SEE</b>		P550595	LF9010	FF5074		370-Z-305H	HF30277
		<b>CLARK</b>		<b>KHD(KLOCKNER-HUMBOLDT-DEUTZ)</b>		P550638	WF2122	FF5074		370-Z-310H	HF30760
		3934763	FF42000	01181917	FF5018	P550667	FS19865	FF5074		370-Z-321H	HF30098
		3942470	FS19579E	Upgrade: FS1221		P55-0943	FF5033	FF5074		370-Z-322H	HF30277
		394521300	FS19579E								

**FLEETGUARD**

**V. Cross Reference by Manufacturer**

**HYDAC**

MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	
370-Z-323H	HF30760	4144966	AF1843	<b>FLUITEK</b>		<b>FUCHS</b>		<b>HALLA</b>		H60WK01	FF5018	
920-P-212	HF30220	42032856	AF1843	PO60081-2U71	HF35184	5411656493	FF5074	3903640	FF5052	Upgrade: FS1221		
R640H1606A	HF30109	42481020	AF1843	<b>FLUXFILTER</b>		<b>FULLER</b>		Upgrade: FS1251		H60WK03	FF5074	
<b>FAMEL</b>		<b>FIAT HITACHI</b>		DS4102	FF5018	123106145400	89422COR	532026000	FF5052	<b>HEULIEZ</b>		
FCS-46	FF5018	<b>SEE FORD</b>		Upgrade: FS1221		<b>GENERAC CORP.</b>		Upgrade: FS1251		<b>SEE RENAULT TRUCKS</b>		
Upgrade: FS1221		<b>SEE NEW HOLLAND</b>		<b>FLXIBLE</b>		642380325	FF5226	<b>HAMM</b>		01213202	FF5074	
<b>FARR</b>		151821124	FF5018	97-5205-00317	FF5074	<b>GIESSE</b>		00234575	FF5018	Upgrade: FS1221		
062891-002	AH8503	Upgrade: FS1221		<b>FORD</b>		CNH-814/1	FF5018	Upgrade: FS1221		<b>HANOMAG-</b>	000 294 3301	LF3977
62891-2	AH8503	72110719	HF7955	1432-209	AF25841	<b>GMC</b>		<b>HANSCH</b>		0003038001	AF25895	
C-62891-2	AH8503	76049606	AF25454	9613344	FF5095	<b>SEE GENERAL MOTORS</b>		<b>HENSCHEL</b>		0003038101	FF5471	
<b>FAUN-FRISCH</b>		76049607	AF25468	A780X-9150-AA	FF5018	<b>SEE CHEVROLET/GMC</b>		114-924-143	FF5018	0004694001	AF26199	
147-0394	FF5018	76195115	LF3349	Upgrade: FS1221		12339911	FF5095	Upgrade: FS1221		<b>HIFI</b>		
Upgrade: FS1221		76596097	HF28836	CFD-509	FF5095	14061325	916001A <sub>OR</sub>	194-932-159	FF5018	<b>HIFI/JURA FILTRATION</b>		
4134-772	FF5018	<b>FIAT KOBELCO</b>		E5HN-9N327-AA	FF5095	14067430	86666M <sub>OR</sub>	Upgrade: FS1221		SN70197	FS19865	
Upgrade: FS1221		76613940	FF5108	E6HZ-9155-F	FF5095(2)	15998574	AF25258 <sub>OR</sub>	194-993-159	FF5018	<b>HINO</b>		
4795-772	FF5018	<b>FIAT ALLIS</b>		E6HZ-9365-A	FF5095	20510778	FF5206	Upgrade: FS1221		156072051A	LF3818	
Upgrade: FS1221		1909132	AF1843	E7HN9N327AA	FF5095	Upgrade: FF5333		711-983-614	FF5018	156072170A	LF3818	
<b>FBN FILTRI</b>		2098616	FF5226	E7HZ9365A	FF5095	25010251	LF796 <sub>OR</sub>	000-922-783	FF5018	15607-2190	LF16226	
FN1.01534	FF5018	61144392	FF5018	Upgrade: FS1251		25010792	LF780 <sub>OR</sub>	Upgrade: FS1221		178013440A	AF4878	
Upgrade: FS1221		Upgrade: FS1221		<b>FORD FINISCODE</b>		25011140	FF5033	Upgrade: FS1221		23304-89102	FF5226	
<b>FENDT</b>		72098616	FF5226	5004780	FF5018	25011214	FF5033	<b>HARMO</b>		FS1962490	FS19624	
F100001160243	FF5018	8031565	AF25484	Upgrade: FS1221		25011240	FF5018	S863	FF5018	<b>HITACHI</b>		
Upgrade: FS1221		8032066	AF25485	6106753	FF5018	Upgrade: FS1221		Upgrade: FS1221		4390060	AF976	
F181200060030	FF5018	<b>FIATAGRI</b>		Upgrade: FS1251		<b>HASTINGS</b>		832	FF5018	4391205	AF975M	
Upgrade: FS1221		<b>SEE NEW HOLLAND</b>		<b>FRAM</b>		832-A	FF5018	Upgrade: FS1221		76613940	FF5108	
<b>FENWICK</b>		1930820	FF5018	CA-4818	AF4509	Upgrade: FS1221		832-A	FF5018	F0122940	FF5018	
<b>SEE GULDNER</b>		Upgrade: FS1221		CA4977	AF25446	25012003	FF5052	Upgrade: FS1221		Upgrade: FS1221		
8103084	FF5018	<b>SEE FIAT HITACHI</b>		CA9246SY	AF25497	Upgrade: FS1251		843	FF5033	L4286130	AF25412	
Upgrade: FS1221		1930891	FF5018	CA9516	AF26152	25012428	HF7947 <sub>OR</sub> 6	847	FF5226	L4390060	AF976	
9831622	FF5018	Upgrade: FS1221		CA9676	AF26158	25042562	AF25316 <sub>OR</sub> 6	AF2376	AF26154	L4391205	AF975M	
Upgrade: FS1221		<b>FILCA</b>		CA9758	AF25955	25055046	FF5026 <sub>OR</sub>	AF2377	AF26153	<b>HONDA</b>		
<b>FIAAM</b>		FC-86-US	FF5018	CA9871	AF25858	25055052	FF5026 <sub>OR</sub>	AF2399	AF25967	15400ZJ1004	LF3462	
FA5820ECO	FF5463	Upgrade: FS1221		CA9872	AF4060	25059463	AF25256 <sub>OR</sub>	CFA1219	AF26131	<b>HOUGH</b>		
FD-4932	FF5074	<b>FILPRO</b>		CA9872SY	AF1843	25121468	FF5199 <sub>OR</sub>	FF1008	FF5052	161624	FF5052	
FL6664	AF4018	SOE 5-5	HF6539	CA9874SY	AF25521	25168082	AF25259 <sub>OR</sub>	Upgrade: FS1251		Upgrade: FS1251		
FL6664	AF4018	<b>FILT</b>		CA9874SY	AF25521	7984867	FF5018	FF1093	FF19579E	FF1110	FF5052	
FL6757	AF25446	G1110EC	FF5018	CA9900	AF26159	Upgrade: FS1221		FF1116	FF5095	Upgrade: FS1251		
FL6817	AF25320	Upgrade: FS1221		CS8941	FS19579E	88944151	AF26159	FF1119	FF5226	FF1116	FF5095	
FL19096	AF25317	<b>FILTRON</b>		CS9864	FS19844	89017342	LF3945	FF1159	FF19684E	FF1159	FF19684E	
FL19097	AF26261	PP845/2	FF5018	HP5	LF678	Upgrade: FS1221		FF1160	FF19579E	FF1160	FF19579E	
FL19098	AF26246	Upgrade: FS1221		P-3711	FF5033	222-4651	FF180	FF1164SPS	FF1003	Upgrade: FS19596		
FL19100	AF26241	<b>FINN</b>		P-4102	FF5018 <sub>OR</sub>	<b>GOODYEAR</b>		Upgrade: FS19596		FF1165SPS	FF19701	
FL19101	AF26204	FFUP-531	FF5018	Upgrade: FS1221		170041	FF5018	FF-832	FF5018	FF-832	FF5018	
FL19105	AF26165	Upgrade: FS1221		<b>FILTRON</b>		<b>GREGOIRE</b>		Upgrade: FS1221		FF-843	FF5033	
FL19106	AF26245	PP845/2	FF5018	P4102A	FF5052	170041	FF5018	FF-847	FF5226	FF-847	FF5226	
FP-4683	FF5018	Upgrade: FS1221		Upgrade: FS1251		<b>GREYFRIARS</b>		<b>HAULOTTE</b>		<b>SEE PINGUELY</b>		
Upgrade: FS1221		<b>FILTRON</b>		P4102RP	FF5018	801S	FF5018	029002427002910	HF35294	<b>HEAVY DUTY AIR</b>		
FP-4932	FF5074	PP845/2	FF5018	Upgrade: FS1221		Upgrade: FS1221		20-400-VS	900272A	20-400-VS	900272A	
FT-4802	FF5018	Upgrade: FS1221		P-4688	FF5052	<b>GROVE</b>		20-500-VS	900273A	20A-400	90356A	
Upgrade: FS1221		<b>FINN</b>		Upgrade: FS1251		9-414-100790	FF5052	20A500	90358A	<b>HENGST</b>		
FT-4932	FF5074	FFUP-531	FF5018	P-4766	FF5226	Upgrade: FS1251		E175HD129	LF16046	E175HD129	LF16046	
FT-5006	FF5226	Upgrade: FS1221		P-6503	FF5095	<b>GROVE</b>		E566L	AF4895	E566L	AF4895	
FT5800	CS41000	<b>FISPA</b>		P7514	FF5226	9-414-100790	FF5052	H167WK	FF5647	H167WK	FF5647	
FT5801	CS41005	FNE212	FF5018	P7572	FF5226	Upgrade: FS1221		H215WK	FS19821	H215WK	FS19821	
FT5806	CS41003	Upgrade: FS1221		P9865	FF5012	<b>GUARDIAN</b>		H286WK	FF5045	H286WK	FF5045	
FT5823	FF5625	FNE315	FF5018	<b>FRANKLIN</b>		<b>SEE GARDNER</b>		H60WK	FF5018	H60WK	FF5018	
FT5824	FS19605	Upgrade: FS1221		1507034	FF5052	G03-3124	FF5033	Upgrade: FS1221		Upgrade: FS1221		
PA7260	AF25754	<b>FLEETGUARD</b>		Upgrade: FS1251		<b>GUIOT</b>		<b>SEE RENAULT TRUCKS</b>		000 294 3301	LF3977	
PA7267	AF4916	RS4993	AF25708M	<b>FREIGHTLINER</b>		GF.4102	FF5018	0003038001	AF25895	0003038101	FF5471	
PC8116	AF25695	RS5301	AF25898	<b>SEE ENGINE SECTION</b>		Upgrade: FS1221		0240R040W	ST2090	0240R100W	ST2089	
PC8134	AF25733	<b>FLO-LINE</b>		ABPN83328345	AF25697	<b>GULDNER</b>		2600R020BN3HC/B6	ST1316	<b>SEE RENAULT TRUCKS</b>		
<b>FIAT</b>		<b>SEE AIR REFINER</b>		<b>SEE ENGINE SECTION</b>		9831622	FF5018	<b>SEE RENAULT TRUCKS</b>		<b>SEE RENAULT TRUCKS</b>		
<b>SEE FIAT-ALLIS</b>		PF-5018	FF5018	<b>SEE ENGINE SECTION</b>		Upgrade: FS1221		<b>SEE RENAULT TRUCKS</b>		<b>SEE RENAULT TRUCKS</b>		
<b>SEE IVECO</b>		Upgrade: FS1221		<b>SEE ENGINE SECTION</b>		<b>SEE RENAULT TRUCKS</b>		<b>SEE RENAULT TRUCKS</b>		<b>SEE RENAULT TRUCKS</b>		
1902132	AF1843			<b>SEE ENGINE SECTION</b>		<b>SEE RENAULT TRUCKS</b>		<b>SEE RENAULT TRUCKS</b>		<b>SEE RENAULT TRUCKS</b>		
2394637	AF1843			<b>SEE ENGINE SECTION</b>		<b>SEE RENAULT TRUCKS</b>		<b>SEE RENAULT TRUCKS</b>		<b>SEE RENAULT TRUCKS</b>		

Error! Reference source not found.



**FLEETGUARD**

**V. Cross Reference by Manufacturer**

**PACCAR**

MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.
LFF3520	FF246	SE210	AF1843	WK8145	FS19865	<b>MICRO</b>		3358MP	FF5018(12)OR	15208-13201	LF781OR
LFF3521	FF5052	<b>MANITOU</b>		WK8146	FS19794	02193	LF3513	Upgrade: FS1221		152085Y00	LF3434OR
Upgrade: FS1251		137147	FF5018	WK842/18	FF5647	T-2207	LF16226	Upgrade: FS1251	FF5052(12)	15208-LA40A	LF16015
LFF-3806	FF5095	Upgrade: FS1221		WK 9165 X	FS1280	<b>MILLER</b>		3390	FF5226	16401-LA40A	FF5485
LFF8762	FS19580	473729	FF5052	WK950/19	FS19821	192744	FF5135	3648	FS19865	16546-18000	AF1666OR
LFP-943F	FF5033	Upgrade: FS1251		WK970/2	FF5322	192938	AF25436	3719	FS19684E	16546-99461	AF25453
LFW2126	WF2126	<b>MANITOWOC</b>		ZR905Z	CS41008	192939	AF25497	3777	FF5052	16546-V0100	AF4615OR
PH59	LF3945	<b>SEE GROVE</b>		<b>MASSEY-FERGUSON</b>		197899	LF3376	Upgrade: FS1251		3172840K00	HF7924
Upgrade: LF16104		<b>SEE POTAIN</b>		1057951-M1	FF5018	<b>MITSUBISHI</b>		4043	FF246	<b>OMT</b>	
T660	TF15046	4133920	FF5052	Upgrade: FS1221		ME063505	AF1863M	<b>NELSON</b>		OMTI 05 EN A	
<b>M FILTER</b>		Upgrade: FS1251		1072419-M1	FF5052	<b>MOPAR</b>		<b>SEE COAST WINSLOW</b>		ST1024HHAND	
MP450	FF5018	1076749-M1	FF5052	Upgrade: FS1251		05015581AA	FS19579E	<b>SEE WINSLOW</b>		<b>ONAN</b>	
Upgrade: FS1221		Upgrade: FS1251		194932159	FF5018	5015581AB	FS19579E	70459C	AF25647	0140-3071	AF25538
MP450P	FF5018	2862361-M1	FF5018	Upgrade: FS1221		<b>MORBARK</b>		871362B	AF26336	149-2251	FF5052
Upgrade: FS1221		Upgrade: FS1221		2871513-M1	FF5018	29215-327	FF5052	871363B	AF26337	Upgrade: FS1251	
<b>M.A.N.</b>		2871513-M2	FF5018	Upgrade: FS1221		29241-032	FF5018	900272A	900272A	0149-2794	FF149
<b>SEE NEOPLAN</b>		3282454-M91	FF5226	Upgrade: FS1221		<b>MOTORCRAFT</b>		900273A	900273A	0155-2064-04	41240OR
35A255017	FF5018	3621280M1	FF5052	Upgrade: FS1251		EFG25	FF5018	70459C	AF25647	0155-2065-07	41380OR
Upgrade: FS1221		53952M91	14214T	Upgrade: FS1221		Upgrade: FS1221		871363B	AF26337	0155-2065-10	41384OR
51.05504-0104	LF3327	TRA8023395	FF5226	Upgrade: FS1221		FD-3372	FF5095	900272A	900272A	0155-2694-01	44540SOR
51.12503.0012	FF5018	<b>MASTE</b>		Upgrade: FS1221		FD-68	FF5018	900273A	900273A	0155-2695-05	44682FOR
Upgrade: FS1221		D53F	FF5018	Upgrade: FS1221		FD-823	FF5033	<b>NEM</b>		0155-2696-05	44782FOR
51.12503.0035	FF5018	DK53F	FF5018	Upgrade: FS1221		FG-68	FF5018	<b>NEW HOLLAND</b>		0185-5471	LF3490
Upgrade: FS1221		Upgrade: FS1221		<b>MAZDA</b>		Upgrade: FS1221		<b>SEE NEW HOLLAND</b>		187-0012	FF5052
81.08304-0098	AF25523	<b>MC CORMICK</b>		0636-23-581	FF144	45310041A	FF5018	<b>SEE FORD</b>		Upgrade: FS1251	
81.08304-0099	AF25756	<b>SEE LANDINI</b>		<b>MC MEXICO AUTOBUS</b>		4531022	FF5018	<b>SEE FIAT</b>		187-0015	FF5018
81.08405-0018	AF26327	MCJ903640	FF5052	394202023	90366BOR	4531041	FF5018	149700730824	HF28919	Upgrade: FS1221	
81.12503.0035	FF5018	Upgrade: FS1251		Upgrade: FS1221		Upgrade: FS1221		276515	FF5018	118005	FF5018
Upgrade: FS1221		<b>MCI MEXICO AUTOBUS</b>		7413562	FF5018	<b>MOXY</b>		Upgrade: FS1221		Upgrade: FS1221	
<b>M.W.M.</b>		7413562/00	FF5018	Upgrade: FS1221		051212	FF5018	283119	FF5018	1427219	FF5113
42264	89422COR	Y104004T0000	FF5018	Upgrade: FS1221		Upgrade: FS1221		Upgrade: FS1221		1449793	FF5052
605411420020	FF5018	<b>MENGELE</b>		Upgrade: FS1221		4531041	FF5018	47131179	HF6553	Upgrade: FS1251	
Upgrade: FS1221		98024258	FF5018	Upgrade: FS1221		Upgrade: FS1221		47135975	AF25484	1451543	FF5226
605411880015	FF5018	98041804	FF5018	Upgrade: FS1221		6.011.022	HF30003	73180723	FF5074	1470029	FF5074
Upgrade: FS1221		Upgrade: FS1221		<b>MERCEDES-BENZ</b>		6011022	HF30003	76094056	AF25352	1471808	FF5113
<b>MACDON</b>		6110920101	FF5647	<b>MECALAC</b>		6012001	HF30212	81802003	HF6189	1487627	AF25748
25851	FF5052	63061840225	LF3769	7413562	FF5018	63000117	HF30220	82034441	AF25457	1487628	AF25749
Upgrade: FS1251		6A110920101	FF5647	Upgrade: FS1221		<b>MP FILTRI</b>		83977315	FF5052	1499387	FF5113
<b>MACK</b>		<b>MERLE</b>		Upgrade: FS1221		<b>SEE MP PRODUCTS</b>		Upgrade: FS1251		29493	FF5018
2681850	90368BOR	D00055	FF5113	Upgrade: FS1221		6.011.022	HF30003	47131179	HF6553	Upgrade: FS1221	
Upgrade: FS1221		<b>MITSUBISHI</b>		Upgrade: FS1221		CS050A03	HF6539	47135975	AF25484	047737	FF5074
<b>MAHLE</b>		<b>MP PRODUCTS</b>		Upgrade: FS1221		CS050A03A	HF6539	73180723	FF5074	<b>OSHKOSH</b>	
778 8508	HF30290	6003004	HF35184	Upgrade: FS1221		CS050A06	HF6539	76094056	AF25352	1583410	49340BOR
891 026 SMX10 NBR		6012001	HF30212	Upgrade: FS1221		CU 630 A10N	ST2267	81802003	HF6189	1946300	90359COR
Upgrade: HF30290		63000117	HF30220	Upgrade: FS1221		F008	HF28755	283119	FF5018	<b>P &amp; H</b>	
965 050 9155	ST1523	48100451	FF5018	Upgrade: FS1221		STR100-1-BG1-M90	ST1017	Upgrade: FS1221		<b>HARNISCHFEGE</b>	
965 051 0155	ST1524	Upgrade: FS1221		Upgrade: FS1221		STR100	ST1008	47131179	HF6553	<b>R</b>	
HC18	ST1422	<b>MORSE</b>		Upgrade: FS1221		<b>MP PRODUCTS</b>		47135975	AF25484	1046Z382	FF5052
HX 77 ECO	HF35074	6110920101	FF5647	Upgrade: FS1221		6003004	HF35184	73180723	FF5074	Upgrade: FS1251	
HX 78	HF6202	63061840225	LF3769	Upgrade: FS1221		6012001	HF30212	76094056	AF25352	1046Z511	FF5018
Upgrade: HF6344		6A110920101	FF5647	Upgrade: FS1221		63000117	HF30220	81802003	HF6189	Upgrade: FS1221	
KC186	FS1254	<b>MOTORCRAFT</b>		Upgrade: FS1221		<b>NANNIDIESEL</b>		82034441	AF25457	1046Z639	FF5018
KC214	FS19821	D53F	FF5018	Upgrade: FS1221		48100451	FF5018	83977315	FF5052	Upgrade: FS1221	
KC 215	FF5206	DK53F	FF5018	Upgrade: FS1221		Upgrade: FS1221		47131179	HF6553	221046Z67	FF5018
Upgrade: FF5333		Upgrade: FS1221		Upgrade: FS1221		<b>NAPA</b>		47135975	AF25484	Upgrade: FS1221	
KC24	FF5018	<b>MOTOR VM</b>		Upgrade: FS1221		2798	AF25955	76094056	AF25352	221046Z67	FF5018
Upgrade: FS1221		45310041A	FF5018	Upgrade: FS1221		3124	FF5033	81802003	HF6189	Upgrade: FS1221	
KC6	FF5018	4531022	FF5018	Upgrade: FS1221		3195	FF5095	1499387	FF5113	<b>P.B.R.</b>	
Upgrade: FS1221		4531041	FF5018	Upgrade: FS1221		3358	FF5018OR	29493	FF5018	BG-1503	FF5018
KL174	FF5647	<b>MP FILTRI</b>		Upgrade: FS1221		Upgrade: FS1221		Upgrade: FS1251		Upgrade: FS1221	
LKS43	AF1843	<b>SEE MP PRODUCTS</b>		Upgrade: FS1221		6003004	HF35184	47131179	HF6553	Upgrade: FS1221	
LX 7120	AF26284	6.011.022	HF30003	Upgrade: FS1221		6012001	HF30212	73180723	FF5074	1487627	AF25748
LX7210/7	AF26327	6011022	HF30003	Upgrade: FS1221		63000117	HF30220	76094056	AF25352	1487628	AF25749
LX809	AF4959	CS050A03	HF6539	Upgrade: FS1221		<b>MP PRODUCTS</b>		81802003	HF6189	1499387	FF5113
LXS43/1	AF1843	CS050A03A	HF6539	Upgrade: FS1221		6003004	HF35184	82034441	AF25457	29493	FF5018
OC230	LF3657	CS050A06	HF6539	Upgrade: FS1221		6012001	HF30212	83977315	FF5052	Upgrade: FS1221	
OC474	LF3977	CU 630 A10N	ST2267	Upgrade: FS1221		63000117	HF30220	47131179	HF6553	047737	FF5074
OC 550	LF3595	F008	HF28755	Upgrade: FS1221		<b>NANNIDIESEL</b>		47135975	AF25484	<b>OSHKOSH</b>	
OX 348D ECO	LF16046	STR100-1-BG1-M90	ST1017	Upgrade: FS1221		48100451	FF5018	76094056	AF25352	1583410	49340BOR
OX359D	LF16042	STR100	ST1008	Upgrade: FS1221		Upgrade: FS1221		81802003	HF6189	1946300	90359COR
		<b>MP PRODUCTS</b>		Upgrade: FS1221		<b>NEW HOLLAND</b>		83977315	FF5052	<b>P &amp; H</b>	
		6003004	HF35184	Upgrade: FS1221		<b>NH CONSTRUCTION S</b>		47131179	HF6553	<b>HARNISCHFEGE</b>	
		6012001	HF30212	Upgrade: FS1221		<b>SEE FIAT</b>		47135975	AF25484	<b>R</b>	
		63000117	HF30220	Upgrade: FS1221		149700730824	HF28919	73180723	FF5074	1046Z382	FF5052
		<b>NANNIDIESEL</b>		Upgrade: FS1221		276515	FF5018	76094056	AF25352	Upgrade: FS1221	
		48100451	FF5018	Upgrade: FS1221		Upgrade: FS1221		81802003	HF6189	118005	FF5018
		<b>NAPA</b>		Upgrade: FS1221		283119	FF5018	82034441	AF25457	Upgrade: FS1221	
		2798	AF25955	Upgrade: FS1221		47131179	HF6553	83977315	FF5052	1451543	FF5226
		3124	FF5033	Upgrade: FS1221		47135975	AF25484	47131179	HF6553	1470029	FF5074
		3195	FF5095	Upgrade: FS1221		73180723	FF5074	76094056	AF25352	1471808	FF5113
		3358	FF5018OR	Upgrade: FS1221		76094056	AF25352	81802003	HF6189	1487627	AF25748
		Upgrade: FS1221		Upgrade: FS1221		81802003	HF6189	82034441	AF25457	1487628	AF25749
		Upgrade: FS1251		Upgrade: FS1221		82034441	AF25457	83977315	FF5052	1499387	FF5113
		<b>NISSAN</b>		Upgrade: FS1221		83977315	FF5052	47131179	HF6553	29493	FF5018
		<b>SEE DATSUN</b>		Upgrade: FS1251		47131179	HF6553	47135975	AF25484	Upgrade: FS1221	
		11810-60U00	3959518SOR	Upgrade: FS1221		47135975	AF25484	73180723	FF5074	1451543	FF5226

Error! Reference source not found.

**PACCAR**

**V. Cross Reference by Manufacturer**

**FLEETGUARD**

MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.
<b>PALL</b>		FA3213	AF25235	<b>POWERPART</b>		F53125	FF5018	8701175600	FF5018	<b>SCHAEFF</b>	
AC8300FKN8Z	HF35184	FA3261	AF1795M	AM043906	FF5018	Upgrade: FS1221		Upgrade: FS1221		5411656567	FF5113
AC8300FUN8Z	HF35184	FA3263	AF1752M	Upgrade: FS1221		F54424	FF5052	<b>REXWORKS</b>		5501648497	AF25539
HC6400FKN16H	HF30109	FA3293	AF350K	<b>PPM</b>		Upgrade: FS1251		298-06528-68	HF7530	<b>SCHROEDER</b>	
HC8300FDN8Z	HF35184	FA3300	AF353K	<b>PRINS MOTOREN</b>		F55212	FS19579E	Upgrade: HF30113		SBF-0241D-Z5B	
HC8300FDS8Z	HF35184	FA3316	AF1643	P10.15221.4308.0	FF5226	F55360	FS19579E	<b>RICHIER</b>		ST1047	
HC8300FKN16H	HF30109	FA3317	AF1929	<b>PTI</b>		F59265	FF5033	552352602	FF5018	<b>SDMO</b>	
HC8300FKN8Z	HF35184	FA3323	AF4039	9314475	ST1641	HF3030KFB	HF30262	Upgrade: FS1221		330242229	LF3781
HC8300FUN8Z	HF35184	FA3407	AF1842	9314476	ST1642	HF3030KFB	HF30263	<b>RIKER</b>		Upgrade: LF3931	
HC8300FDS4H	HF30212	FA3408	AF1840	9314477	ST1643	HF3050KFB	HF30294	TTA400	90356A	Upgrade: LF9931	
HC9020FDP4Z	HF30382	FA3417	AF4631	AHF3-060-GU-B	HF30006	HF3050KFB	HF30295	TTA500	90358A	330244261	LF3957
HC9020FUP4Z	HF30382	FA3424	AF971	F4E-070-GC-B	HF6776	PC-42	FF5018	VS400	900272A	330361667	FS19865
HC9601FDF8H	HF30480	FA3428	AF977	FK-010-GG-V	HF30382	Upgrade: FS1221		VS500	900273A	Upgrade: FS1221	
HC9606FDS4H	HF30212	FA3435	AF1841	H3-060-GF-V	HF30585	PER-262F	FF5226	<b>ROMA</b>		<b>SEPARATION TECHNOLOGIES</b>	
HC9606FUS4H	HF30212	FA3436	AF1843	HF3-015-GU-B	HF30000	PER-265F	FF5033	CBOS-3640	FF5052	3960MGHB04	
<b>PARKER</b>		FA3470	AF1802	HF3-030-GU-B	HF30002	PER-336-F	FF5018	Upgrade: FS1251		3F27GGHB09	
<b>SEE PARKER</b>		FA3492	AF4057	HF3-030-GU-V	HF30003	Upgrade: FS1221		CBOS-970	FF5018	HF30220	
<b>SEE HEAVY DUTY AIR</b>		FA3494	AF4135	HF3030KFB	HF30263	PG-015-GH	ST1424	Upgrade: FS1221		<b>SF FILTRES</b>	
1010010012	HF6306	FA3500	AF1812	HF3050KFB	HF30294	PG-015-GU	ST1518	<b>RACOR</b>		SK 3279	FS19865
927664	HF35184	FA3596	AF25066	HF3050KFB	HF30295	<b>RENALT AGRICULTURE</b>		PFF19579	FS19579E	SK3350	FS19868
935144	HF30109	FA3642	AF424	HF3050KFB	HF30295	<b>SEE CLAAS</b>		R120-D-MER	FS19737	<b>SISU</b>	
935144Q	HF30109	FA3643	AF418	HF3-060-GU-B	HF30006	60 05 019 578	FF5018	<b>RENAULT</b>		<b>SEE AGCO</b>	
FC2006F005	HF6539	FA3644	AF472	P64-150-HF-B	HF30109	60 05 700 453	FF5018	<b>AGRICULTURE</b>		836440991	
FC 5000 Q010 BS	ST1000	FA3646	AF1733K	P83-100-HF-V	HF35184	77 01 456 928	FF5018	<b>SEE BUCYRUS-ERIE</b>		LF3467	
FC 7252 A005 BS	ST1047	FA3650	AF820M	P83-100-KF-V	HF35185	77 01 456 953	FF5018	<b>RYCO</b>		406041	
PR3152	ST1047	FA3651	AF490M	P83-150-KF-B	HF30309	Upgrade: FS1221		Z-132	FF5226	FF5018	
<b>PARTEK FOREST</b>		FA3688	AF4910	P83-250-KF-B	HF30341	Upgrade: FS1221		Z-75	FF5018	Upgrade: FS1221	
445152	90354COR	FA3695	AF853	PG-015-CH	ST1450	Upgrade: FS1221		<b>SAAB MOTOR</b>		<b>SOFIMA</b>	
	90354COR	FA3696	AF863M	PG-015-GH	ST1424	Upgrade: FS1221		729565	LF3945	CA151EFC1	
<b>PERKINS</b>		FA3697	AF978	PG-015-GU	ST1518	Upgrade: FS1221		Upgrade: LF16104		HF6539	
<b>SEE POWERPART</b>		FA3698	AF4058	PG-015-HH	ST1529	<b>RENAULT D.M.A.</b>		<b>SAKURA</b>		<b>SOFRANCE</b>	
26569054	FF5018	FA3699	AF25064	PG-015-HU	ST1545	<b>SEE CLAAS</b>		C-1316	LF16226	CH0609101481Y00	
Upgrade: FS1221		FA3702	AF4060	PG-030-GU	ST1520	60 05 000 383	FF5018	FC-5704	FF5018	ST1936	
SEV551F/4	AF26207	FA4004	AF4920	PG-030-KH	ST1407	60 05 000 788	FF5074	FC-7903	FF5052	<b>SOPARIS</b>	
<b>PERMATIC</b>		FA4200	AF409K	PG-030-KU	ST1413	60 05 028 977	FS19868	Upgrade: FS1251		SEE MAHLE	
EL3252	AF1666	FA4300	AF250	PG-080-GU	ST1430	<b>RENAULT TRUCKS</b>		T-2207	LF16226	CVN-198	
ELG5506	FF5074	FA4301	AF456	PG-080-JU	ST1527	<b>SEE RENAULT V.I.</b>		<b>SAMBRON</b>		Upgrade: FS1221	
ELG5519	FF5297	FA4302	AF4657	RSE50-10	HF6710	5001 829 755	FF5126	39732.3		FF5018	
FA0800	AF828COR	FA4303	AF4658	RSE55-10	HF7947COR	50 01 866 519	MK13119	Upgrade: FS1221		FF5226	
	AF1800	FA4400	AF4747COR	Upgrade: HF7980	HF6177	74 20 972 291	FF5507	Upgrade: FS1221		<b>SSANG YONG</b>	
FA1024	AF1881		AF25293M	RSE55-3	HF7947COR	<b>RENAULT V.I.</b>		2.4319.500.1	FF5018	3903640	
FA1371	AF4565	<b>PETERBILT</b>		Upgrade: HF7980	HF6177	<b>SEE RENAULT V.I.</b>		Upgrade: FS1221		Upgrade: FS1251	
FA1372	AF4566	<b>SEE ENGINE SECTION</b>		Upgrade: HF7980	HF6177	5001 829 755	FF5126	<b>SAMSUNG</b>		35005	
FA1434	AF25285	1411054		Upgrade: HF7980	HF6177	50 01 866 519	MK13119	9912-03640		35369	
FA1439	AF4662	90082ACOR		Upgrade: HF7980	HF6177	74 20 972 291	FF5507	Upgrade: FS1251		35370	
FA1443	AF1882	<b>PF PROGRAMMA</b>		Upgrade: HF7980	HF6177	<b>RENAULT TRUCKS</b>		A77470-2L	FF5052	<b>STANADYNE</b>	
FA1456	AF25061	PPF50920		Upgrade: HF7980	HF6177	<b>SEE RENAULT V.I.</b>		Upgrade: FS1251		35005	
FA1462	AF25251	AF25352		Upgrade: HF7980	HF6177	5001 829 755	FF5126	<b>SAME</b>		35369	
FA1474	AF25286	<b>PHILLIPS 66</b>		Upgrade: HF7980	HF6177	5000 790 570	FF5074	2.4319.500.1		FF5052	
FA1519	AF25065	P-358		Upgrade: HF7980	HF6177	5000 790 759	FF5018	Upgrade: FS1221		FF5018	
FA1535	AF25249M	Upgrade: FS1221		Upgrade: HF7980	HF6177	<b>RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
FA1566	AF4841	<b>PLY LOCO</b>		Upgrade: HF7980	HF6177	0022852800	FF5074	9.28.005.17		FF5018	
FA1567	AF4867	1409628		Upgrade: HF7980	HF6177	4033156710	FF5018	Upgrade: FS1221		FF5018	
FA1893	AF308	90356COR		Upgrade: HF7980	HF6177	<b>RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
FA2219	AF25319	<b>POCLAIN</b>		Upgrade: HF7980	HF6177	5000 790 759	FF5018	9.28.039.17		FF5018	
FA3101	AF4842	1505-26		Upgrade: HF7980	HF6177	<b>RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
FA3102	AF4521	Upgrade: FS1221		Upgrade: HF7980	HF6177	0022852800	FF5074	9.28.146.17		FF5018	
FA3105	AF4583M	1505-64		Upgrade: HF7980	HF6177	4033156710	FF5018	Upgrade: FS1221		FF5018	
FA3108	AF1804	Upgrade: FS1221		Upgrade: HF7980	HF6177	<b>RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
FA3109	AF1798	G01505-26		Upgrade: HF7980	HF6177	5000 790 759	FF5018	9.28.146.17		FF5018	
FA3110	AF4522	Upgrade: FS1221		Upgrade: HF7980	HF6177	<b>RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
FA3111	AF4523	G01505-88		Upgrade: HF7980	HF6177	5001 829 755	FF5126	9.28.146.17		FF5018	
FA3115	AF4638	Upgrade: FS1221		Upgrade: HF7980	HF6177	50 00 814 227	FF5074	Upgrade: FS1221		FF5018	
FA3119	AF4575	G150564		Upgrade: HF7980	HF6177	5001020327	AF4841	9.28.146.17		FF5018	
FA3169	AF25333	Upgrade: FS1221		Upgrade: HF7980	HF6177	5006002224	FS1242B	Upgrade: FS1221		FF5018	
FA3171	AF25382	G01505-88		Upgrade: HF7980	HF6177	<b>PUROLATOR</b>		9.28.146.17		FF5018	
FA3199	AF830	Upgrade: FS1221		Upgrade: HF7980	HF6177	<b>SEE PTI</b>		Upgrade: FS1221		FF5018	
<b>PORTEC INC.</b>		220		9313338	HF30382	<b>SEE RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
		AF403		9314659	HF35184	<b>SEE RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
				A35595	AF26159	<b>SEE RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
				A78103	AF1843	<b>SEE RENAULT V.I.</b>		Upgrade: FS1221		FF5018	
				F50262	FF5226	<b>SEE RENAULT V.I.</b>		Upgrade: FS1221		FF5018	

**FLEETGUARD**

**V. Cross Reference by Manufacturer**

**ZETTELMEYER**

MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.	MFRS. MODEL	OUR NO.
<b>STEYR-DAIMLER-PUCH</b>		<b>TOWMOTOR</b>		VPD 6035	FF5018	9912-03640	FF5052	33195	FF5095		
132.00.00.70726	LF3467	<b>SEE CATERPILLAR</b>		Upgrade: FS1221		Upgrade: FS1251		33358	FF5018		
<b>STILL</b>		363992	HF7947 <sup>OR6</sup>	<b>VERMEER</b>		<b>VOLVO</b>		Upgrade: FS1221			
0133748	FF5074	069-0826	AF25966M	107612-001	FF5052	<b>CONSTRUCTION EQUIPMENT</b>		33358MP	FF5018(12) <sup>OR</sup>		
1687004	FF5074	<b>TOYOTA</b>		Upgrade: FS1251		11708551	LF3914	Upgrade: FS1221			
<b>SULLAIR</b>		17741-F9860-71	AF25337M	218420-073	FF5226	<b>VOLVO PENTA</b>		Upgrade: FS1251			
68415814	FF5226	17801-64010	AF4959	<b>VERSATILE</b>		20405827	AF25723	33390	FF5226		
68560937	AF25526	23303-87037	FF5226	<b>SEE NEW HOLLAND</b>		3825133	FF5074	33411	FS1287		
68560938	AF25484	23304-89102	FF5226	88834	FF5052	3825133-6	FF42000 <sup>OR</sup>	33648	FS19865		
<b>TAMROCK</b>		90915-10003	LF3614	Upgrade: FS1251		FF5074		33668	FS19868		
80094909	FF5018	S156072190	LF16226	<b>VETUS</b>		3827643	AF26249	336-P	FF5018		
Upgrade: FS1221		<b>TRUCKCARE</b>		VD60092	FF5113	3840335	FF5442	Upgrade: FS1221			
81849359	FF5018	07-2-0101-0	FF5018	VD60210	FF5074	3850559	LF653	33719	FS19684E		
Upgrade: FS1221		<b>TRUCKEX</b>		<b>VIC</b>		Upgrade: LF3488		33777	FF5052		
85187419	HF6420	<b>SEE GOERLICHS</b>		FC707A	FF5226	<b>VOLVO-BM</b>		Upgrade: FS1251			
<b>TATA</b>		B400V	900272A	<b>VICKERS</b>		<b>SEE VOLVO</b>		33786	FS19843		
2525 1813 01 29	LF16051	B500V	900273A	V0411V2V05	HF35184	14213939	FF5018	33920	FF5206		
<b>TEC-FIL</b>		<b>UCC</b>		<b>VME (VOLVO</b>		Upgrade: FS1221		Upgrade: FF5333			
PS-73/1	FF5018	<b>HYDRAULICS</b>		<b>BMMICH./EUCLI</b>		14213939-3	FF5018	46919	AF25858		
PSC73/1	FF5018	UC-2439	ST1426	<b>D)</b>		Upgrade: FS1221		49088	AF26103		
Upgrade: FS1221		UC-2449	ST1427	M1992367	FF5018	<b>WALKER MFG.</b>		49131	AF25723		
<b>TECALEMIT-TJ</b>		<b>UFI</b>		Upgrade: FS1221		35621	89522B <sup>OR</sup>	49132	AF25724		
FF2089	FF5018	24.307.00	FF5018	<b>VOGELE</b>		36419	900272A	524043	FF246		
Upgrade: FS1221		Upgrade: FS1221		4624082176	AF4060	36420	900273A	57137	LF16106		
<b>TECNOCAR</b>		24.358.00	FF5018	4624082177	AF1843	41005	89105A <sup>OR</sup>	57202MP	LF16102		
A160	AF25754	Upgrade: FS1221		4624082223	AF25723	41098	89230A <sup>OR</sup>	57259	LF9008		
A24	AF1666	24.999.01	FS19821	4624082224	AF25724	41099	89232A <sup>OR</sup>	57866	ST2073		
A259	AF25320	27 306 00	AF976	<b>VOLVO</b>		41367	89105A <sup>OR</sup>	<b>WOODGATE</b>			
A26	AF1649	53 066 00	AF25829	11708550	LF3827	41368	89105A <sup>OR</sup>	WGA1529	AF25614		
A434	AF25446	<b>V.A.G.</b>		2097 2293	FF5507	41538	900118A <sup>OR</sup>	WGF5018	FF5074		
A642	AF4018	<b>(VOLKSWAGEN,</b>		241672	FF5018	41638	900059A <sup>OR</sup>	WGF5033	FF5033		
A691	AF25841	<b>AUDI)</b>		Upgrade: FS1221		42336	900064A <sup>OR16</sup>	WGF5106	FF5226		
A927	AF4916	<b>SEE PORSCHE</b>		2416725	FF5074	42944	900057A <sup>OR</sup>	WGF723	FF5074		
A927	AF4916	06A 115 561B	LF785	243004	FF5018	44112	900060A <sup>OR16</sup>	WGH24005DH	ST1047		
N297	FF5198	<b>VALMET</b>		Upgrade: FS1221		<b>WAUKESHA</b>		<b>YALE &amp; TOWNE</b>			
RN45	FF5018	1992367	FF5052	243004-9	FF5018	169180-E	AF25977 <sup>OR</sup>	1500229-00	AF492 <sup>OR</sup>		
Upgrade: FS1221		Upgrade: FS1251		3132887	FF5018	350433	FF5018	<b>YANMAR</b>			
RN45B	FF5018	8353 31343	FF5018	Upgrade: FS1221		Upgrade: FS1221		129150-35150	LF3657		
Upgrade: FS1221		Upgrade: FS1221		3946774	90388P <sup>OR</sup>	<b>WESTERN</b>		129150-35151	LF3996		
<b>TEREX</b>		<b>VALMET</b>		Upgrade: FS1221		E0410-V1-U10	HF35184	165000-34500	FF5626		
<b>SEE EUCLID</b>		1992367	FF5052	3946776	90386P <sup>OR</sup>	E3041-V-U03	HF30382	165000-34510	LF3730		
15246949	ST1768	Upgrade: FS1251		Upgrade: FS1221		<b>WESTERN STAR</b>		2330387307	FF5226		
<b>THERMO-KING</b>		8353 31343	FF5018	3946777	90386P <sup>OR</sup>	170014406	FS19738	<b>ZETTELMEYER</b>			
<b>SEE INGERSOLL-RAND</b>		Upgrade: FS1221		Upgrade: FS1251		<b>WHITE</b>		2141290	HF7947 <sup>OR</sup>		
11-9182	LF9030	<b>VALTRA</b>		3946777	90368P <sup>OR</sup>	30-3437574	FF5052	22854657	FF5052		
12.0428	AF1976	<b>TRAKTOR</b>		Upgrade: FS1221		Upgrade: FS1251		Upgrade: FS1251			
<b>TIMBCO</b>		<b>SEE VALMET</b>		3946778	90368P <sup>OR</sup>	30-3483541	FF5018	4053800	FF5018		
15811	FF5052	<b>SEE AGCO</b>		Upgrade: FS1221		Upgrade: FS1221		Upgrade: FS1221			
Upgrade: FS1251		20331343	FF5018	3946778	90366P <sup>OR</sup>	30-312801817	FF5052	40538001	FF5018		
<b>TIMBERJACK</b>		Upgrade: FS1221		Upgrade: FS1221		Upgrade: FS1251		0 405 63502	FF5113		
<b>SEE JOHN DEERE</b>		<b>VAPORMATIC</b>		447803A	86147B <sup>OR</sup>	312801817	FF5052	4058800	FF5018		
413330	FF5052	<b>SEE JOHN DEERE</b>		466987	FF5074	Upgrade: FS1251		Upgrade: FS1221			
Upgrade: FS1251		CPD6031	FF5052	466987-3	FF5074	<b>WIRTGEN</b>		MU5380	FF5018		
8413330	FF5052	Upgrade: FS1221		466987-5	FF5074	1940	FF231	Upgrade: FS1221			
Upgrade: FS1251		CPD6035	FF5018	4770170-1	FF5074	3181	AF25065	40538001	FF5018		
<b>TOKYO ROKI</b>		Upgrade: FS1221		7243004	FF5018	50978	FF234	Upgrade: FS1221			
2281251100	FF5226	VPD6031	FF5052	Upgrade: FS1221		74332	ST1225	Upgrade: FS1221			
		Upgrade: FS1251		7243004-4	FF5074	<b>WIS CON TOTAL</b>					
				7243004-9	FF5074	<b>POWER</b>					
				79128732	FF5018	26020229	90368B <sup>OR</sup>				
				Upgrade: FS1221		FF5018	90368C <sup>OR</sup>				
				79178732	FF5018	<b>WIX</b>					
				Upgrade: FS1221		24043	FF246				
				8000250	FF5074	24314	AF25660				
				9022854657	FF5052	24786	AF4516				
				Upgrade: FS1251		24792	AF4516M				
						33124	FF5033				